

Areas of Landslides

Mandan Quadrangle, North Dakota

Edward C. Murphy

1999

UNIT DESCRIPTIONS

 Geology Undifferentiated

QUATERNARY SYSTEM

RECENT/PLEISTOCENE

 Landslide Deposits
Sedimentary rock disturbed (out of place) due to slope failure.

Geologic Symbols

 Known contact between two geologic units

Landslides identified on this quadrangle were mapped from stereo pairs, black and white 1:20,000 scale aerial photographs flown between 6-21-58 and 9-7-58. As a result these maps can be used to identify areas that are vulnerable to slope failure, but are not an up to date assessment of all landslides for the area.


Other Features

 Interstate Highway


 State Highway

 Paved Road

 Unpaved Road



Mandan Quadrangle, North Dakota



Lambert Conformal Conic Projection
1927 North American Datum
Standard Parallels 46° 45' 00" and 46° 52' 30"

