

Areas of Landslides

Snider Hill Quadrangle, North Dakota

Christopher A. Maike

2024

Areas of landslides were investigated within this quadrangle based on a review of county historical aerial photography flown in 1957 by the United States Department of Agriculture (USDA). Additional data sources include digital orthophotography from the USDA National Agriculture Imagery Program (NAIP) flown in July to August 2022 and the North Dakota Geological Survey LiDAR Map Series, which compiles raw data flown in November 2021 from the North Dakota State Water Commission. From this investigation, no landslides were mapped within the quadrangle.

ROAD CLASSIFICATION

- Expressway

Secondary Hwy

Ramp
- Local Connector


Local Road

4WD
- Interstate Route

US Route

State Route

Scale 1:24,000





Lambert Conformal Conic Projection
North American 1983 Datum
USGS 7.5 Minute Topo Map

Standard Parallel: 45°52'30"N, 46°0'0"N
NGVD 1988
Contour Interval 20 Feet



2017 Magnetic North
Declination at Center of Sheet



Snider Hill Quadrangle, North Dakota