

Areas of Landslides

Lemmon Quadrangle, North Dakota

Christopher A. Maike
&
Levi D. Moxness

2025

UNIT DESCRIPTIONS

-  Geology Undifferentiated
-  Area Not Mapped

Areas of landslides were investigated within this quadrangle based on a review of county historical aerial photography flown in July 1957 by the United States Department of Agriculture (USDA). Additional data sources include digital orthophotography from the USDA National Agriculture Imagery Program (NAIP) flown in August 2022 and the North Dakota Geological Survey LiDAR Map Series, which compiles raw data flown in August 2022 from the North Dakota State Water Commission. From this investigation, no landslides were mapped within the quadrangle.

ROAD CLASSIFICATION

- Expressway  Local Connector 
- Secondary Hwy  Local Road 
- Ramp  4WD 
-  Interstate Route  US Route  State Route

